

**Software Version:** N/A

**Firmware Version:** V22.03.02

**Database Version:** V22.00.03

**Bootloader Version:** V18.00.06

## Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

## Affected Product(s)

- (0x3AA)3030RSv1

## New / Added Features & Functions

- Support vehicle up to 2022
- Added QR Code to get even more with the RepairSolutions2 mobile app.
  - Gain free access to:
    - Vehicle Health Reports
    - Verified Fixes and Parts Required
    - Predicted Repairs
- Added tool ID

## Fixes / Updates

- Fix – VIN Decode: BMW, VW, Hyundai Kia
- Fix – ABS Read DTC: 2005 Subaru Subaru Legacy B4, 2.5L, 2019 Subaru Subaru Impreza B4, 2.0L, 1999 Honda Accord L4, 2.3L; SOHC; 16V
- Fix – ABS DTC Definition: 2006-2007 Nissan Xterra
- Fix – UI at Make selection
- Fix – Battery/ Alternator Test

## Product Support

Please visit us at [innova.com/support](http://innova.com/support) for additional information.