

Software Version: N/A

Firmware Version: v22.07.19

Database Version: V22.00.06

Bootloader Version: V18.06.11

Recommended Use:

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

Affected Product(s):

- (0x3D0)3040RSv1-5210v1-6030Pv1

New / Added Features & Functions:

- Support vehicle up to 2022
- Added QR Code to get even more with the RepairSolutions2 mobile app.
 - Gain free access to:
 - Vehicle Health Reports
 - Verified Fixes and Parts Required
 - Predicted Repairs
- Added tool ID

Fixes / Updates:

- Fix - ABS read DTC: 2000 Volvo V40 L4, 1.9L; 2004 Land Rover Discovery; 2012 Mercedes C300

Product Support:

Please visit us at innova.com/support for additional information.