

Software Version: N/A

Firmware Version: V22.00.01

Database Version: V22.00.05

Bootloader Version: V18.05.01

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- (0x3C2)5160rs-5610

New / Added Features & Functions

- Support vehicle up to 2022
- New features under OEM Diagnostics:
 - Added an *OEM Enhanced Live Data* landing page to stream ECM and TCM.
- New and improved OBD2 Live Data PID list with quick selection to record data and submit it to the server via RS2 App.
- New expanded tool functions:
 - Added more *Active Test* and *Special Function* for the engine system
 - Support 7 vehicle makes with the most function: GM, FORD, CHRYSLER, HONDA, TOYOTA, HYUNDAI, NISSAN
- Added QR Code to get even more with the RepairSolutions2 mobile app.
 - Gain free access to:
 - Vehicle Health Reports
 - Verified Fixes and Parts Required
 - Predicted Repairs
- Added tool ID

Fixes / Updates

- Fix - ABS, SRS, or TPMS read DTC: 2010 Chrysler Jeep Compass, 2019 Mercedes Sprinter 3.0 V6 2500 4x4, 2005 GM Pontiac GTO 6.0L LS2.
- Fix - DPF Reset: 2015 GM Chevrolet Silverado 6.6, 2010 GM Chevrolet Express G4500s, 2017 GM Chevrolet SILVERADO 2500 6.6L DIESEL.
- Fix - Transmission Fluid Temperature: 2004 GM Chevrolet Trailblazer 4.2L.
- Fix - Battery reset: 2009 BMW 328i.
- Fix - ABS live data: 2007 Cadillac CTS, 3.6L.

Product Release Notes

Scan Tools and Code Readers

- Fix - Special function/Crankshaft Pos. Variation Learn: 2008 GM Hummer H3.
- Fix - Special function/Cylinder Power Balance: 2017 GM Chevrolet Trailblazer L6, 4.2L.
- Fix - Service reset/ABS Bleeding 2010 Toyota Prius, 2006 Mini Cooper.

Product Support

Please visit us at innova.com/support for additional information.