Product Release Notes

Software Version: N/A

Firmware Version: v22.07.25

Database Version: V22.00.07

Bootloader Version: V18.06.11

Recommended Use:

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

Affected Product(s):

- (0x3B3)5100RS-5414

New / Added Features & Functions:

- Support vehicle up to 2022

- New and improved OBD2 Live Data PID list with quick selection to record data and submit it to the server via RS2 App.

- Added QR Code to get even more with the RepairSolutions2 mobile app.

    ➢ Gain free access to:
        ▪ Vehicle Health Reports
        ▪ Verified Fixes and Parts Required
        ▪ Predicted Repairs

- Added tool ID

Fixes / Updates:

- Fix - Service reset/Battery reset: 2014 Mini Cooper; 2016 Ford Escape; 2017 Mini Cooper Clubman L4, 1.5L F54; 2017 BMW 5 Series L6, 3.0L; 2017 BMW X3 L6, 3.0L (N55) xDrive35i F25

- Fix - PCM read DTC: 2003 Ford Explorer V6, 4.0L

- Fix - ABS read DTC: 2000 Volvo V40 L4, 1.9L; 2004 Land Rover Discovery; 2012 Mercedes C300

- Fix - Service check: 2014 Mini Cooper Countryman L4, 1.6L ALL4 R60

Product Support:

Please visit us at innova.com/support for additional information.